

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER

Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:						
OGM	Gregg Galecki Environmental Scientist III					
Company	Patrick D. Collins Resident Agent					

Inspection Report

Permit Number:	C0070012		
Inspection Type:	COMPLETE		
Inspection Date:	Tuesday, June 29, 2004		
Start Date/Time:	6/29/2004 11:00:00 AM		
End Date/Time:	6/29/2004 2:00:00 PM		
Last Inspection:	Wednesday, May 26, 2004		

Inspector: <u>Gregg Galecki, Environmental Scientist III</u>
Weather: <u>Overcast, rain showers, ~65 deg. F. No wind</u>

InspectionID Report Number: 317

Accepted by: dhaddock

7/28/2004

Permitee: NEVADA ELECTRIC INVESTMENT CO
Operator: NEVADA ELECTRIC INVESTMENT CO
Site: WELLINGTON PREPARATION PLANT

Address: 330 E 400 S STE 6, PO BOX 337 SPRINGVILLE UT 84663

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acreages	Mineral Ownership	Types of Operations		
1,573.50	Total Permitted	☐ Federal	☐ Underground		
392.00	Total Disturbed	☐ State	Surface		
	Phase I	☐ County	☐ Loadout		
	Phase II	☐ Fee	✓ Processing		
	Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Inspector's Signature

Gregg Galecki Environmental Scientist III

Inspector ID Number: 48

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Utah!

Thursday, July 01, 2004

Date

Permit Number: C0070012 Inspection Type: COMPLETE

Inspection Date: Tuesday, June 29, 2004

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.

- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	V		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		~	
4.d	Hydrologic Balance: Water Monitoring	V		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		V		
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		V	
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation	✓		V	
12.	Backfilling And Grading		V		
13.	Revegetation		V		
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check	✓		✓	
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other		V		

Permit Number: C0070012 Inspection Type: COMPLETE

Inspection Date: Tuesday, June 29, 2004

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

No new permits, changes, transfers, renewals or sales have been submitted since the last inspection. The current DOGM permit term is 10 Dec 99 through 9 Dec 04. The current UPDES permit term is 1 May 03 - 30 Apr 08.

2. Signs and Markers

Signs were inspected and found to be legible and fulfill the regulatory requirements. Markers were spot-checked and found to be in-place.

3. Topsoil

The topsoil pile located on the east side of the property was evaluated; no signs of instability were noted.

4.a Hydrologic Balance: Diversions

Diversions were inspected and found to be functioning as designed. Minor maintenance and repairs will be conducted during the 3rd quarter.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment Pond inspections were conducted on 9 Mar 04 for the first quarter 2004. Ponds include the Roadside, Auxillary, Dryer, Loadout, Pipeline, Upper Refuse, Lower Refuse and Clearwater Ponds. Inspections for the 2nd quarter 2004 were conducted, but not all the paperwork was available.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fencing and strawbales were spot-checked and found to be functioning as designed.

4.d Hydrologic Balance: Water Monitoring

The 1st quarter water monitoring data was collected on 9 Mar 04 and submitted electronically to the Division database. Minor anomalies were noted in the data that will be followed up by the NEICO water monitoring contractor.

4.e Hydrologic Balance: Effluent Limitations

No discharges were noted in the 1st and 2nd quarters of 2004. Data for the 1st quarter was submitted in hard copy to DWQ and electronically to the Division database.

Permit Number: C0070012 Inspection Type: COMPLETE

Inspection Date: Tuesday, June 29, 2004

Page 4 of 4

7. Coal Mine Waste, Refuse Piles, Impoundments

Refuse Piles were inspected on 9 Mar 04 for the 1st quarter 2004. For added dust suppression, the operator smoothed out rough edges and significantly reduced the slopes on the coal fines piles located on the east side of the property. The slopes have been reduced to the point a water truck can now access the piles to apply a surfactant if necessary. No signs of instability were noted. Photos of the slope reduction are available in the M: drive under the April and May inspection dates.

8. Noncoal Waste

The vast majority of equipment and buildings have been removed from the east side of the property. Days prior to the DOGM inspection, a contractor removed pumps from the pumphouse on the southeast end of the property. Without the company's approval the contractor also removed the pumphouse structure, exposing access to the lower levels of the pumphouse. Both NEICO and DOGM personnel identified this as a safety concern and immediately took steps to secure the site from a safety perspective. Additional measures to fully secure the site will take place in the coming weeks. Photos are available in the Division M: drive under the inspection date.

11. Contemporaneous Reclamation

With the exception of mining equipment being removed from the site, no earthmoving reclamation activities have been conducted.

16.b Roads: Drainage Controls

Road drainage controls were inspected and found to be functioning as designed.

19. AVS Check

An AVS check was conducted during the 2nd Quarter 2004. No pending or outstanding violations were noted during the search.

20. Air Quality Permit

An air quality permit was initially issued 10 May 96. A copy of the permit is on site and available for review.

21. Bonding and Insurance

A copy of the current bond insurance was on site; the bonded value is \$4.904 million. A copy of the liability insurance was on site; term is 9 Feb 04 - 9 Feb 05.